

Pressure Vs Torque Conversion Chart <i>Titan T10 Square Drive Tool</i>				
Pressure			Torque	
Psi	<i>Ft-Lb</i>	Bar	<i>Kgm</i>	<i>Nm</i>
1500	1662	103	229	2254
1600	1773	110	245	2404
1800	1994	124	275	2704
2000	2236	138	309	3032
2200	2460	152	339	3335
2400	2683	166	370	3638
2600	2907	179	401	3942
2800	3130	193	432	4245
3000	3365	207	464	4563
3200	3589	221	495	4867
3400	3814	235	526	5171
3600	4038	248	557	5476
3800	4262	262	588	5780
4000	4456	276	615	6042
4200	4679	290	646	6344
4400	4902	304	676	6647
4600	5124	317	707	6949
4800	5347	331	738	7251
5000	5588	345	771	7577
5200	5812	359	802	7880
5400	6035	373	833	8184
5600	6259	386	864	8487
5800	6482	400	895	8790
6000	6717	414	927	9108
6200	6941	428	958	9412
6400	7165	442	989	9715
6600	7389	455	1020	10019
6800	7613	469	1051	10323
7000	7746	483	1069	10504
7200	7967	497	1099	10804
7400	8189	511	1130	11104
7600	8410	524	1161	11404
7800	8631	538	1191	11704
8000	8867	552	1224	12024
8200	9089	566	1254	12324
8400	9310	580	1285	12625
8600	9532	593	1315	12925
8800	9754	607	1346	13226
9000	10075	621	1390	13662
9200	10299	635	1421	13965
9400	10523	649	1452	14269
9600	10747	662	1483	14572
9800	10971	676	1514	14876
10000	11067	690	1527	15007