

<b>Pressure Vs Torque Conversion Chart</b>					
<b><i>Titan T1 Square Drive Wrench</i></b>					
<b>Pressure</b>			<b>Pressure</b>		<b>Torque</b>
<b>Psi</b>	<b><i>Ft-Lb</i></b>		<b>Bar</b>	<b><i>Kgm</i></b>	<b><i>Nm</i></b>
1500	197		103	27	267
1600	210		110	29	285
1800	236		124	33	321
2000	271		138	37	367
2200	298		152	41	404
2400	325		166	45	441
2600	352		179	49	477
2800	379		193	52	514
3000	411		207	57	557
3200	438		221	60	594
3400	465		235	64	631
3600	493		248	68	668
3800	520		262	72	705
4000	549		276	76	745
4200	577		290	80	782
4400	604		304	83	820
4600	632		317	87	857
4800	659		331	91	894
5000	686		345	95	930
5200	714		359	98	968
5400	741		373	102	1005
5600	769		386	106	1042
5800	796		400	110	1079
6000	824		414	114	1118
6200	852		428	118	1155
6400	879		442	121	1192
6600	907		455	125	1230
6800	934		469	129	1267
7000	962		483	133	1305
7200	990		497	137	1342
7400	1017		511	140	1379
7600	1045		524	144	1417
7800	1072		538	148	1454
8000	1098		552	151	1489
8200	1125		566	155	1526
8400	1153		580	159	1563
8600	1180		593	163	1600
8800	1208		607	167	1637
9000	1233		621	170	1672
9200	1261		635	174	1709
9400	1288		649	178	1747
9600	1315		662	182	1784
9800	1343		676	185	1821
10000	1359		690	188	1843