

Pressure Vs Torque Conversion Chart				
<i>Titan T5 Square Drive Tool</i>				
Pressure	Torque		Pressure	Torque
Psi	Ft-Lb		Bar	Kgm Nm
1500	816		103	113 1107
1600	871		110	120 1180
1800	979		124	135 1328
2000	1101		138	152 1493
2200	1212		152	167 1643
2400	1322		166	182 1792
2600	1432		179	198 1942
2800	1542		193	213 2091
3000	1656		207	229 2246
3200	1767		221	244 2396
3400	1877		235	259 2546
3600	1988		248	274 2695
3800	2098		262	290 2845
4000	2230		276	308 3023
4200	2341		290	323 3174
4400	2452		304	338 3326
4600	2564		317	354 3477
4800	2675		331	369 3628
5000	2790		345	385 3783
5200	2902		359	400 3935
5400	3013		373	416 4086
5600	3125		386	431 4237
5800	3237		400	447 4389
6000	3353		414	463 4547
6200	3465		428	478 4699
6400	3577		442	494 4850
6600	3689		455	509 5002
6800	3800		469	524 5153
7000	3891		483	537 5276
7200	4002		497	552 5427
7400	4114		511	568 5578
7600	4225		524	583 5729
7800	4336		538	598 5880
8000	4492		552	620 6092
8200	4605		566	635 6244
8400	4717		580	651 6396
8600	4829		593	666 6549
8800	4942		607	682 6701
9000	5056		621	698 6856
9200	5168		635	713 7008
9400	5281		649	729 7160
9600	5393		662	744 7313
9800	5505		676	760 7465
10000	5605		690	774 7601